

January 30, 1975

Mr. Burton Wenner  
216 West Barnes Ave.  
Napoleon, Ohio 43545

Subject: Complaint issued by Mrs. Mary Sauber at  
204 Filmore St. for possible violation  
of City Ordinance No. 464 at 202 Filmore  
St.

Dear Mr. Wenner:

The subject residence was inspected by me on January 27,  
1975 and the following facts were evident:

1. On the Northeastern side of the dwelling, the down-  
spout is not properly installed to handle water  
drainage.
2. The present installation is also a hazardous con-  
dition because of its location near a means of  
egress in case of a fire.

As per discussed during our meeting on January 30, 1975,  
you, or your wife, as the owner of 202 Filmore St., are in  
direct violation with City Ordinance No. 464 which regulates  
roof water downspouts and storm water drainage.

Therefore, you must comply with any one of the three  
approved methods noted on the attached sketch within fourteen  
(14) days from the date of this notice or the City of Napoleon  
will have no other alternative but to enforce the penalties  
set forth in Section 6 and 7 of City Ordinance No. 464.

Very truly yours,

Thomas W. Terranova  
City Building Inspector  
Engineering Department

TWT/cv

Enclosure

cc: Mrs. Mary Sauber

COPY

cc: Mrs. Mary Garber

Enclosure

TWT/cv

Engineering Department  
City Building Inspector  
Thomas W. Terisnow

Very truly yours,

set forth in Section 6 and 7 of City Ordinance No. 484. Will have no other alternative but to enforce the penalties (14) days from the date of this notice or the City of Napoleon approved methods noted on the attached sketch of the fifteen therefore, you must comply with any one of the three

roof water downspouts and storm water drains.

direct violation with City Ordinance No. 484 which requires you, or your wife, as the owner of 302 Filmore St., are in violation per discussed during our meeting on January 30, 1932,

2. address in case of a fire.
3. The present installation is also a violation of Ordination because of its location near a means of drainage.
4. On the Northeastern side of the dwelling, the downspout is not properly installed to handle water

1932 and the following facts were evident:  
The subject residence was inspected by me on January 27,


Dear Mr. Wenner:

2f.  
of City Ordinance No. 484 at 302 Filmore  
304 Filmore St. for possible violation  
Complaint issued by Mrs. Mary Garber at

Napoleon, Ohio 43342  
316 West Barnes Ave.  
Mr. Buford Wenner

JANUARY 30, 1932

Mr. Wenner changed routing  
of downspouts on week-in of  
1/25/75.



1/52/12

2d specimens only missing of  
the monna. Spindley contains

NAPOLEON, OHIO

SKETCH SHOWING  
THREE APPROVED METHODS  
OF DISCONNECTING DOWNSPOUTS  
FROM SANITARY SEWERS. ALSO,  
APPROVED METHOD OF HANDLING  
STORM AND SURFACE WATER IN  
NEW CONSTRUCTION.

