

# PROJECT RECORD FORM

JOB NUMBER 1 Hudson Dr.

DATE	REMARKS
7/31/55	Inspected house to determine what has to be done to bring it up to code.
	1. Raise house & relay cement foundation.
	2. Replace wall studs where approx 75% of studs to be replaced.
	3. Floor joist disrotted & wormy 20% to be replaced.
	4. Not enough windows to meet Light & Ventilation requirements.
	5. No bathroom, kitchen, water pipe or electric in building.
	6. Ridge beam in garage spliced.
	7. Balcon framing, needs fire stopping.
	8. Entire interior finish needed.
	9. Finish front brick work by front door.
	House should be removed & rebuilt only R. G. Hayman

# PROJECT RECORD FORM

JOB NUMBER 1 Hudson Dr.

DATE	REMARKS
7/31/55	Inspected house to determine what has to be done to bring it up to code.
	1. Raise house & relay cement foundation.
	2. Replace wall studs where spliced 75% of studs to be replaced.
	3. Floor joist dry rotted & wormy 20% to be replaced.
	4. Not enough windows to meet Light & Ventilation requirements.
	5. No bathroom, kitchen, water pipes or electric in building.
	6. Ridge beam in garage spliced.
	7. Balloon framing, needs fire stopping.
	8. Entire interior finish needed.
	9. Finish front brick work by front door.
	House should be removed & rebuilt over.
	R.G. Gayman

# PROJECT RECORD FORM

JOB NUMBER 1 HUDSON DR.

DATE	REMARKS
7/31/55	Inspected house to determine what has to be done to bring it up to code.
	1. Raise house & relay cement foundation.
	2. Replace wall studs where spliced 75% of studs to be replaced.
	3. Floor joist dry-rotted & wormy 20% to be replaced.
	4. Not enough windows to meet Light & Ventilation requirements.
	5. No bathroom, kitchen, water pipes or electrical in building.
	6. Ridge beam in garage spliced.
	7. Balcon framing, needs fire stopping.
	8. Entire interior finish needed.
	9. Finish front brick work by front door.
	House should be removed & rebuilt only R. G. Hayman