

Repairs by Bob Cordes

2-20-97

N

upstream
main hole

connection made with hydrolic cement†
Brick main

39.2'

6" PVC SDR 35
C 4.0 f/l

6"

ferrule

6" C10
C 3.4 f/l

----- = 6" vit left in place

240 Mainline
W. Mainline

W. Mainline