


DYE TEST AND LOCATE. ALL TAPS AND LINES 1689 through 1725

2013




1753 Observed


1711 Dye Tested

Nowater

1	2	3	4	5	6
---	---	---	---	---	---

27	28	29	30	31	32
----	----	----	----	----	----





Setup 1	Surveyor Roger Darr	Certificate # U-906-3742	System Owner
Drainage	Survey Customer		
P/O #	Date 2013/07/12	Time 8:06	Street Oakwood
City	Further location details		
Start 1800 OAKWOOD	Rim to Invert	Grade to Invert	Rim to grade Ft
Finish 1722 OAKWOOD	Rim to Invert	Grade to Invert	Rim to grade Ft
Use Sanitary	Direction Downstream	Flow control	Media No 1
Shape Circular	Height 10	Width	Year Cleaned 2013/07/09
Material Polyvinyl Chloride	Joint length	Year laid	Year rehabilitated
Lining	Year laid	Year rehabilitated	Weather Saturated
Purpose Routine Assessment	Cat		
Additional info	Structural	O&M	Hydraulic
Location Yard	Miscellaneous		Construcional

Pipe Graphic Report of PSR 1800 OAKWOOD X for City of Napoleon