

623 SECOND STREET

SECOND STREET

Investigation of illegal sewer connections revealed two (2) illegal connections. All downspouts have been corrected and are in compliance at this time.

2015



623

CAPPED
& GULVED
BELOW
GRADE

SCANNED