OHIO BASIC INCIDENT REPORT

State of Ohio
State Fire Marshal
FORM 902F
(Revised 4/4/80)

Fill In This Report
In Your Own Words

Napoleon Fire Department

A	1 FDID: 35015	Incident No.: 8510102123	Exp.: 1	Mo.: 05	Day: 11	Year: 85	Day of the Week: Saturday 7	Alarm Time: 09:06	Time "In Service": 1/0106	
B	CORRECT ADDRESS: 1075 Glenwood Ave.							Zip Code: 0104315415	Census Tract: 0101010100	
C	Occupant Name: St. Pauls Lutheran Church (School)						Telephone: 592-3535	Room or Apt.: 3rd Grade		
D	Owner Name: St Pauls Lutheran Church	Address: 1075 Glenwood Ave.						Telephone: 592-3535		
E	Method of Alarm from Public: 592-0055 11	Type of Situation Found: Structure fire (class room) 11								
F	Type of Action Taken: Ventilation 11	Co. Inspection District: 10100	Shift: 3	No. Alarms: 1	Mutual Aid: 1 ☐ Rec'd ☐ Given					
G	No. Fire Service Personnel Used at Scene: 10116	No. Engines Used at Scene: 10103	No. Aerial Apparatus Used at Scene: 10101	No. Other Vehicles Used at Scene: 10100						
H	2 No. Incident-related Injuries * Fire Service: 10101 Others: 10100	No. Incident-related Fatalities Fire Service: 10101 Others: 10100	Complex: School 1210							
I	Fixed Property Use: Parochial School 12211	Mobile Property Type: N A 11								
J	Area of Fire Origin: Classroom 113	Level of Fire Origin: 3 ft. 11	Termination Stage: Flame Stage 13							
K	Equipment Involved in Ignition (If any): Heater for Fish Aquarium 112	Form of Heat of Ignition: Overheated wires 1217								
L	Type of Material Ignited: Plastic Lamp Cover 1410	Form of Material Ignited: Electrical wire 611	Ignition Factor: thermostat failure 1511							
M	Structure Type: two or more uses 12	Construction Type: Masonary 11	Construction Method: Site Built 11							
N	Extent of Flame Damage: Object of origin 11	Extent of Smoke Damage: Room of origin 13	Extent of Water Damage: None 19							
O	Extent of Fire Control Damage: None 19	Detector Performance: None 18	Sprinkler Performance: None 18							
P	IF FLAME SPREAD BEYOND ROOM OF ORIGIN: N A 11	Type of Material Generating Most Flame	Avenue of Flame Travel: N A 11							
Q	IF SMOKE SPREAD BEYOND ROOM OF ORIGIN: N A 11	Type of Material Generating Most Smoke	Avenue of Smoke Travel: N.A. 1							
R	Method of Extinguishment									
S	Estimated Total Dollar Loss: 10101011810	Property Damage Classification: 1500 to 2,000 13	Time from Alarm to Agent Application: 3 minutes 13							

COMPLETE ON ALL INCIDENTS

COMPLETE IF CASUALTY OR FIRE

ALL IGNITIONS

COMPLETE IF FIRE FOR STRUCTURE FIRE ONLY

ALL FIRES

COMPLETE ON ALL INCIDENTS

*List name, age, sex, and description of injury for each casualty on form 902G

T

Officer in Charge (Name, Position, Assignment) 161: Norman Behnfeldt, Chief — Date: 5/11

Member Making Report (If Different from Above): Marvin D. Weller Captain — Date: 5/17

Complete Below

U	3 If Mobile Property	Year	Make	Model	Serial No.	License No. (If any)	
V	4 If Equipment Involved in Ignition	Year: UK	Make: UK	Model: UK	Serial No.: UK	Voltage (if any): 120	

REMARKS: