


10970 GLENWOOD AVENUE
ILLEGAL DOWN SPOUT INVESTIGATION



NO ILLEGAL CONNECTIONS WERE
FOUND AT THIS TIME.
INSPECTED BY: MARK SPIESS

2016
N
1"=20'