



#1250
Independence

Date Installed: 4-15-07
 Installed by: McDonald's Constr.
 Inspected by: Rex Moll

Ex. 4" C.I.P.
 4" Feinco
 6" x 4" Reducer
 6"-22° Bend
 6"-45° Bend
 3' Deep FL.

6"-45° Bends
 3.5' Deep FL.
 6"x6"x6" WYE
 6"-45° Bends

Separating Tank 9'ft. Deep

6"-90° Bend
 6"-45° Bend
 6"-22° Bend
 6" cleanout
 3.85' Deep FL.
 6"-22° Bend

6"-45° Bend
 6"-22° Bend
 3.33' Deep FL.
 6"-45° Bend
 6"-22° Bend
 4' Deep FL.

Ex. 4" PVC
 Clean out
 4.5' Deep FL.

6"x6"x6"
 WYE
 5' Deep FL.

Ex. 6" vit

Catch Basin
 Pipe Layed
 directly over
 top of sanitary
 outlet pipe

New C.B.
 outlets into
 Separating Tank

4" vent
 pipe

LOCKER ROOM
 5" CONCRETE FLOOR
 WITH 4" RUBBER BASE

EXISTING BUILDING

1.5' Trench Drain

1.5' Trench Drain

7.6'

1.9'

NEW SIGN LOCATION

60'-0"

35'-0"

38'

3'

4'

7'

07'

6'

17.5'

13'

14.5'

48'

NEW SIGN LOCATION