



Pipe bent  
 45° broken  
 Proper lateral installed by [unclear]  
 when main was installed by [unclear]  
 Repairs made by Bob Cordes 3-6-02

589 Moorings Dr.