

INCIDENT REPORT NAPOLEON FIRE DEPARTMENT

NFIRS-1

[] DELETE
[] CHANGE

A	FDID 35015	INCIDENT NO 00-000474	EXP NO 00	MO 07	DAY 11	YR 00	DAY OF WEEK Tuesday 3	ALARM TIME 02:06:00	ARRIVAL TIME 02:09:00	IN SERVICE 03:11:00	
B	TYPE OF SITUATION FOUND Vehicle Fire						TYPE OF ACTION TAKEN 13 Extinguishment			MUTUAL AID <input type="checkbox"/> Recd <input type="checkbox"/> Given	
C	FIXED PROPERTY USE 1-family Dwelling-year						IGNITION FACTOR 411 Falling Asleep				
D	CORRECT ADDRESS 900 W RIVERVIEW AV NAPOLEON, OH							CO. HE	TWN 9500	ZIP CODE 43545	CENSUS TRACT
E	OCCUPANT NAME GERKEN, GENE							TELEPHONE		ROOM/APT NO	
F	OWNER NAME GERKEN, GENE				ADDRESS 900 W RIVERVIEW AV NAPOLEON, OH				TELEPHONE		
G	METHOD OF ALARM FROM PUBLIC Telephone Direct			TYPE OF ALARM 1 REGULAR		DISTRICT 2 CTY	SHIFT A	STATION 1	NO. ALARMS 1		
H	911 USED E911		PERSONNEL RESPONDED 2 016		ENGINES RESPONDED 002		AERIAL APPARATUS 000		OTHER VEHICLES 002		

ALL INCIDENTS

I	NUMBER OF INJURIES FIRE SERVICE 000			OTHER 000		NUMBER OF FATALITIES FIRE SERVICE 000			OTHER 000	
---	---	--	--	------------------	--	---	--	--	------------------	--

CAS

J	COMPLEX No Complex				MOBILE PROPERTY TYPE 98 Automobile			
K	AREA OF FIRE ORIGIN Pass. Area of Trans. Equip.				EQUIPMENT INVOLVED IN IGNITION 81 No Equipment Involved			
L	FORM OF HEAT OF IGNITION Cigarette		TYPE OF MATERIAL IGNITED 31 Man-made Fiber		FORM OF MATERIAL IGNITED 71 Floor Covering, Surface			
M	METHOD OF EXTINGUISHMENT Preconnect w/Tank Water		LEVEL OF FIRE ORIGIN 5 Grade to +9'		ESTIMATED LOSS 1 10,000		ESTIMATED VALUE 10,000	

ALL FIRES

N	NUMBER OF STORIES			CONSTRUCTION TYPE		
O	EXTENT OF FLAME DAMAGE			EXTENT OF SMOKE DAMAGE		
P	DETECTOR PERFORMANCE			SPRINKLER PERFORMANCE		
Q	IF SMOKE SPREAD BEYOND ROOM OF ORIGIN	TYPE OF MATERIAL GENERATING MOST SMOKE		AVENUE OF SMOKE TRAVEL		
R		FORM OF MATERIAL GENERATING MOST SMOKE				

STRUCTURE

S	IF MOBILE PROPERTY	YEAR 90	MAKE OLDS	MODEL 98	SERIAL NO. 1G3CW5318M430	LICENSE NO. MGW5137
T	IF EQUIPMENT INVOLVED IN IGNITION	YEAR	MAKE	MODEL	SERIAL NO. 2813	

CHECK IF COMMENTS

U	OFFICER IN CHARGE (NAME, POSITION, ASSIGNMENT) HANCOCK, LYNN K/FIRE CHIEF		DATE 07/11/2000
	MEMBER MAKING REPORT (IF DIFFERENT FROM ABOVE) ROHRS, ERIC E/FF/EMT-P		DATE 07/11/2000

**INCIDENT REPORT
NAPOLEON FIRE DEPARTMENT**

A

FDID	INCIDENT NO	EXP NO	MO	DAY	YR	DAY OF WEEK	ALARM TIME
35015	00-000474	00	07	11	00	Tuesday 3	02:06:00

NARRATIVE

Dispatched to an auto fire with victim inside. On arrival victim was on the ground in the yard after being removed by Sheriff's Deputy Mike Bodenbender. Vehicle was fully involved in passenger and engine compartment. Fire was attacked with 1 3/4 preconnected hose line. On investigation and interview, it is believed that Mr. Gerken was at some point in time, prior to the fire, smoking and fell asleep while parked in the driveway. Mr. Gerken had a strong odor about his person not unlike that of alcohol. The fire originated in the passenger compartment on or near the drivers side front edge of the seat. I have no indication to, nor do I suspect arson as a cause of this fire.

07/19/2000 13:20 LYNN HANCOCK