

1"=20'
2-3-2025
Tressler Plumbing
Insp. By: A. Oehl

Replaced broken riser pipe on cleanout and
pulled pieces out of the lateral
that were blocking it

