

WAYNE PARK DR.
CONT: JERRY HILLIS
INSP: MARK SPIESS
JULY 2015



UPON CLOSE INSPECTION,
6\" VIT FOUND TO BE PLUGGED
ABOUT 12\"-18\" FARTHER, SO IT WAS
REMOVED AND A CLEAN OUT INSTALLED

1"=20'