2015

N
1" = 20'

1007 Scott Street

Investigation of illegal sewer connections revealed three (3) illegal connections. All downspouts have been corrected and are in compliance at this time.

CAPPED &
CEMENTED
BELOW GRADE

CEMENTED
SHUT AT
GRADE
(IN CONC.)

1013

x ok

4" c/o

1007

x ok

x

CAPPED &
CEMENTED
BELOW GRADE

1003

Scott
Street