

308 APPIAN AVENUE

SCANNED

Investigation of illegal sewer connections revealed three (3) illegal connections. All downspouts are in compliance at this time.

Downspout Connection Drawing

308

304

