

City of NAPOLEON, OHIO

255 RIVERVIEW AVENUE -- (419) 592-4010

September 4, 1980

Mr. Leland Weirauch 930 W. Main

Mayor

Robert G. Heft

Clerk-Treasurer

Rupert W. Schweinhagen

Members of Council

James Jackson William Young Darel Austermiller Darrell Fox James Zumfelde

City Manager Alan E. Tandy

Law Director Keith Muehlfeld Napoleon, OH 43545

Dear Mr. Weirauch:

Re: 325 Carey

I have received a complaint on your rental property Lawrence Haase, President at 325 Carey. After inspecting the property on Tuesday, September 3, I found the following items in need of repair or removal.

- 1. Gutters and downspouts rotted and deteriorated.
- 2. Downspouts not connected into storm sewers and causing water damage to neighboring properties.
- House in need of repair. Asphalt shingles on exterior walls loose, missing and in need of repair.
- Brick chimney on east of house deteriorated and leaning and a hazard to the neighbor.
- TV antenna laying on roof with no supports.

The above items shall be corrected within 30 days. Chimney shall be removed and rebuilt. The TV antenna shall be removed. Gutters and downspouts shall be removed and replaced with new. Downspouts shall be connected to storm sewers or extended to rear yard. Roof is old and should be replaced.

I hope you will take care of these items as soon as possible.

Yours truly,

Richard G. Hayman Building Commissioner

RGH: dd



City of NAPOLEON, OHIO

255 RIVERVIEW AVENUE -- (419) 592-4010

September 4, 1980

Mr. Leland Weirauch 930 W. Main Napoleon, OH 43545

Re: 325 Carey

Mayor

Robert G., Heft

Clerk-Treasurer

Rupert W. Schweinhagen

Members of Council

James Jackson William Young Darel Austermiller Darrell Fox James Zumfelde

City Manager Alan E. Tandy

Law Director Keith Muehlfeld Dear Mr. Weirauch:

I have received a complaint on your rental property Lawrence Haase, President at 325 Carey. After inspecting the property on Tuesday, September 3, I found the following items in need of repair or removal.

- 1. Gutters and downspouts rotted and deteriorated.
- 2. Downspouts not connected into storm sewers and causing water damage to neighboring properties.
- 3. House in need of repair. Asphalt shingles on exterior walls loose, missing and in need of repair.
- Brick chimney on east of house deteriorated and leaning and a hazard to the neighbor.
- TV antenna laying on roof with no supports.

The above items shall be corrected within 30 days. Chimney shall be removed and rebuilt. The TV antenna shall be removed. Gutters and downspouts shall be removed and replaced with new. Downspouts shall be connected to storm sewers or extended to rear yard. Roof is old and should be replaced.

I hope you will take care of these items as soon as possible.

Yours truly,

Richard G. Hayman

Building Commissioner

RGH:dd