



# City of NAPOLEON, OHIO

255 RIVERVIEW AVENUE — (419) 592-4010

August 14, 1981

**Mayor**  
Robert G. Helt

**Clerk-Treasurer**  
Rupert W. Schweinhagen

**Members of Council**  
Lawrence Haase - President  
James Jackson  
William Young  
Earl A. Steindler  
Gordon E. ...  
James ...

**City Manager**

**Law Director**

Kenneth ...

Mr. Mel Wachtmann  
C. F. Gerken & Sons, Inc.  
2296 N. Scott St.  
Napoleon, OH 43545

Dear Mel:

We have received some complaints of seeding on the Clairmont sewer job, and we have noticed some other areas which appear to need some additional work. Below is a summary of some of those needing attention:

870 Clairmont - Poor top soil preparation of entire yard. The north portion of the main yard only consists of thick crab grass. The south portion of the main yard is satisfactorially grassed but the middle is low and should have additional top soil added.

940 Clairmont - 75% of area has no visible grass. The straw should be raked off, the top soil re-prepared, the area should then be seeded, fertilized and strawed.

950 Clairmont - Same as 940 Clairmont.


800 Clairmont - 40% of area without grass. The same type of additional work could be done as at 940 Clairmont.

850 Clairmont - Same as 800 Clairmont, except 30% of area without grass.

860 Clairmont - Resident has complained of sparse growth.

Please advise me when you have taken action to correct these problems.

Sincerely,

  
Alan Tandy  
City Manager

AT:dd