
INSPECTED BY: MARTY CROSSLAND INVESTIGATION OF ILLEGAL SEWERL CONNECTIONS REVEALED TWO (2) THAT WERE ILLEGAL, BOTH HAVE BEEN CORRECTED AND PROPERTY HAS NO APPARENT LILLEGAL SEWER CONNECTIONS AT THIS TIME.



N 1=20