

FIELD CORRECTION NOTICE

LOCATION 191 OLD CREEK DRIVE PERMIT NO. 01307

ISSUED TO RON ZACHARICH

PERMIT HOLDER AND/OR ALL RESPONSIBLE PARTIES.

NOTICE DELIVERED TO RON ZACHARICH - BOILER

Upon inspection, violations of the C.A.B.O. Sec. R-303 were in evidence.

The following orders are hereby issued for their correction: 12" ANCHOR BOLTS WERE INSTALLED IN VIEW OF 18" WITH 15" PENETRATION INTO THE MASONRY.

IN THE FUTURE ANY MASONRY WALL CHASED UP WITH LESS THAN 15" OF THE ANCHOR BOLTS EXTENDING INTO THE MASONRY OR WITH ANCHOR BOLTS MORE THAN 6" O.D. WILL BE TAKEN DOWN AND REPLACED WITH ANCHOR BOLTS AS REQ. BY THE C.A.B.O.

PLEASE CALL FOR INSPECTION WHEN CORRECTIONS HAVE BEEN COMPLETED. ACCEPTANCE AND APPROVAL BY AN INSPECTOR OF THIS DEPARTMENT IS REQUIRED AND MUST BE CORRECTED

ON OR BEFORE ALL WORK COMPLETING AFTER 3-26-87

DATE 3-26-87 BY ELDON HUBER INSPECTOR

PINK - ORIGINAL COPY WHITE - FIELD COPY YELLOW - FILE COPY

FIELD CORRECTION NOTICE

LOCATION 171 OLD CREEK DRIVE PERMIT NO. 01307

ISSUED TO BOB ZACHRY
PERMIT HOLDER AND/OR ALL RESPONSIBLE PARTIES.

NOTICE DELIVERED TO BOB ZACHRY - SAILOR

Upon inspection, violations of the C.A.B.C.O. Sec. R-303 were in evidence.

The following orders are hereby issued for their correction: 12" ANCHOR BOLTS WERE INSTALLED
IN LIEU OF 18" WITH 15" PENETRATION INTO THE
MASONRY

IN THE FUTURE ANY MASONRY WALL LAID UP
WITH LESS THAN 15" OF THE ANCHOR BOLTS EXTENDING
INTO THE MASONRY OR WITH ANCHOR BOLTS MORE THAN
150MM WILL BE TAKEN DOWN AND RE-CAID WITH

ANCHOR BOLTS AS REQ. BY THE C.A.B.C.O.
PLEASE CALL FOR INSPECTION WHEN CORRECTIONS HAVE BEEN COMPLETED. ACCEPTANCE
AND APPROVAL BY AN INSPECTOR OF THIS DEPARTMENT IS REQUIRED AND MUST BE CORRECTED

ON OR BEFORE 3-26-87

DATE 3-26-87 BY ELOU HUDER INSPECTOR

PINK - ORIGINAL COPY WHITE - FIELD COPY YELLOW - FILE COPY