

120 RAYMOND STREET

DATE: 4-13-15

INSPECTED BY: MARTY CROSSLAND

INVESTIGATION OF ILLEGAL  
DOWNSPOUT CONNECTIONS.  
FOUND TWO (2) DOWNSPOUTS  
TIED TO AN EXISTING CB  
IN THE ALLEY TO THE NORTH.  
ALL OTHER DOWNSPOUTS ARE  
IN COMPLIANCE AT THIS TIME.

4" HDPE INTO  
10" CB IN  
ALLEY

ok  
x

DOWNSPOUT

4" HDPE

120

DOWNSPOUT

ok  
x

ok  
x



6" W.M.

RAYMOND STREET

SCANNED