



designers and manufacturers of coil handling and press feeding automation systems



476 East Riverview
Napoleon, OH 43545-1899
Phone: 419-592-0050
Fax: 419-592-8590

City of Napoleon, Ohio
255 Riverview Avenue
P.O. Box 151
Napoleon, Ohio 43545

August 16, 1994

Attention: Marc Gerken

Dear Mr. Gerken,


In regards to your letter dated August 8 and my phone call to you on August 15 it is our feeling that adding 18" of base to achieve the correct fall for drainage toward the back of our lot would not have been good judgment both economically and design.

Over the past years we have had drainage problems related to this sewer. The city is aware of this and has mentioned to us that it is plugged with roots and needed to be cleaned or replaced. This drainage problem is not the result of our parking lot project; but aging of the city's system.

This problem is nothing new to the city and is not going to get better. Automatic Feed Company is a growing company and I would hope the city is willing to support our growth and not turn their backs on their responsibility.

Sincerely,

AUTOMATIC FEED COMPANY



Peter C. Beck
Vice President

PCB:dco

cc: Mr. James Hershberger
Mr. Jeff Marihugh
Mr. Robert Heft

City of NAPOLEON, OHIO

255 RIVERVIEW AVENUE, P.O. BOX 151
NAPOLEON, OHIO 43545-0151
(419) 592-4010



May 20, 1994

Mayor
Robert G. Heft

Rupp - Rosebrock, Inc.
7-464 U.S. Rt. 24
Liberty Center, Ohio 43532
Attn: Mr. John Rosebrock

Re: Automatic Feed Company
Parking Lot (Phase I)

Members of Council
John E. Church, President
Michael J. DeWit
James Hershberger
Sarah Peper
Terri A. Williams
Travis B. Sheaffer
Charles E. Burgoon

Gentlemen:

We have reviewed your plan submittal concerning the parking/service drive improvements for Phase I of the above referenced project. We have reviewed and approved the lot grades and swale curb, but have comments regarding the storm sewer required for the three (3) new catch basins located in the swale curb.

City Manager
Terry Dunn

There already is an existing twelve (12) inch sewer as you have indicated but this sewer is drastically undersized for its tributary area and we feel that by increasing the volume and intensity of the storm flow will cause more surcharging along the line than previously experienced.

Finance Director
Rupert W. Schweinhagen

We suggest that the three (3) catch basins be drained to the existing catch basin located along the east side of the building. Our only concern with this suggestion, is that we do not know exactly what the size and slope of the outlet sewer is to determine its adequacy.

Law Director
David M. Grahn

City Engineer
Marc S. Gerken

Should you have any questions please call, otherwise we will await your decision regarding the sewer.

Respectfully,

Marc S. Gerken, P.E.
City Engineer

MSG/kr

Encl.

cc: Sonny Helberg



City of NAPOLEON, OHIO

255 RIVERVIEW AVENUE, P.O. BOX 151
NAPOLEON, OHIO 43545-0151
(419) 592-4010

August 8, 1994

Mayor
Robert G. Heft

Automatic Feed Company
476 E. Riverview Ave.
Napoleon, Ohio 43545
Attn: Mr. Peter Beck

Members of Council
John E. Church, President
Michael J. DeWit
James Hershberger
Sarah Peper
Terri A. Williams
Travis B. Sheaffer
Charles E. Burgoon

Re: Parking Lot Improvements

Dear Mr. Beck:

This correspondence is in regard to your recently completed project. As we indicated in our May 20, 1994 correspondence to Rupp-Rosebrock, Inc., your contractor, the existing sewer you are utilizing for drainage is drastically undersized for its tributary area.

City Manager
Terry Dunn

We indicated to Mr. Rosebrock that a new out fall sewer from the point of your hook up to the creek would be the ultimate solution. He indicated that your firm did not wish to spend additional costs. Therefore, please be aware that surcharging could occur and if the improvements do pose a problem, the City of Napoleon will not accept the responsibility.

Finance Director
Rupert W. Schweinhagen

Our long range plans (over the next ten (10) years) is to divert some of this tributary area to another drainage point but this has not been initialed as of yet, due to finances.

Law Director
David M. Grahn

City Engineer
Marc S. Gerken

Respectfully,

Marc S. Gerken, P.E.
City Engineer
Acting City Manager

MSG/kr

Enclosure

cc: Rupp-Rosebrock, Inc.



City of NAPOLEON, OHIO

255 RIVERVIEW AVENUE, P.O. BOX 151
NAPOLEON, OHIO 43545-0151
(419) 592-4010

May 20, 1994

Mayor
Robert G. Heft

Rupp - Rosebrock, Inc.
7-464 U.S. Rt. 24
Liberty Center, Ohio 43532
Attn: Mr. John Rosebrock

Members of Council
John E. Church, President
Michael J. DeWit
James Hershberger
Sarah Peper
Terri A. Williams
Travis B. Sheaffer
Charles E. Burgoon

Re: Automatic Feed Company
Parking Lot (Phase I)

City Manager
Terry Dunn

Gentlemen:

We have reviewed your plan submittal concerning the parking/service drive improvements for Phase I of the above referenced project. We have reviewed and approved the lot grades and swale curb, but have comments regarding the storm sewer required for the three (3) new catch basins located in the swale curb.

Finance Director
Rupert W. Schweinhagen

There already is an existing twelve (12) inch sewer as you have indicated but this sewer is drastically undersized for its tributary area and we feel that by increasing the volume and intensity of the storm flow will cause more surcharging along the line than previously experienced.

Law Director
David M. Grahn

We suggest that the three (3) catch basins be drained to the existing catch basin located along the east side of the building. Our only concern with this suggestion, is that we do not know exactly what the size and slope of the outlet sewer is to determine its adequacy.

City Engineer
Marc S. Gerken

Should you have any questions please call, otherwise we will await your decision regarding the sewer.

Respectfully,

Marc S. Gerken, P.E.
City Engineer

MSG/kr

Encl.

cc: Sonny Helberg