

FIELD CORRECTION NOTICE

LOCATION 1320 W. RIVERVIEW PERMIT NO. 0172 Z

ISSUED TO CYNN RAUSCH

PERMIT HOLDER AND/OR ALL RESPONSIBLE PARTIES:

NOTICE DELIVERED TO CYNN RAUSCH 718 STRONG

Upon inspection, violations of the C.A.B.O. Sec. _____ were in evidence.

The following orders are hereby issued for their correction:

① PROVIDE AN EXHAUST FAN FOR THE FIRST FLOOR ^{112 RATH}
PROVIDE A HANDRAIL ON ONE SIDE OF THE ^{NOT COMPLIANT 5x}
BASEMENT STAIR 30" TO 34" HIGH BOTH FRONT & BACK
STAIRWAYS.

③ PROVIDE A TEMPORARY SCOOP & STEP AT THE
LIVING ROOM, UTILITY ROOM, PORCH AND FRONT
DOORS.

④ PROVIDE A HANDRAIL ALONG THE ENTIRE LENGTH OF
THE 2ND FLOOR STAIR - (FRONT STAIR).

PLEASE CALL FOR INSPECTION WHEN CORRECTIONS HAVE BEEN COMPLETED. ACCEPTANCE AND APPROVAL BY AN INSPECTOR OF THIS DEPARTMENT IS REQUIRED AND MUST BE CORRECTED ON OR BEFORE _____

FIELD CORRECTION NOTICE

LOCATION 1320 W. RIVERVIEW

PERMIT NO. 01222

ISSUED TO CYNG RADICH

PERMIT HOLDER AND/OR ALL RESPONSIBLE PARTIES.

NOTICE DELIVERED TO CYNG RADICH 718 STONEY

Upon inspection, violations of the C.A.B.O.

Sec. _____ were in evidence.

The following orders are hereby issued for their correction:

- ① Provide AN EXHAUST FAN FOR THE FIRST FLOOR NORTH SIDE OF THE HOUSEMENT. 30" TO 34" HIGH BOTH FRONT & BACK STAIRWAYS.
- ② Provide A HANDRAIL ALONG THE ENTIRE LENGTH OF THE 2ND FLOOR STAIR - (FRONT STAIRS).
- ③ Provide A TEMPORARY STOODY STEP AT THE LIVING ROOM, UTILITY ROOM, GARAGE AND FRONT DOORS.
- ④ Provide A HANDRAIL ALONG THE ENTIRE LENGTH OF THE 2ND FLOOR STAIR - (FRONT STAIRS).

ON OR BEFORE _____

PLEASE CALL FOR INSPECTION WHEN CORRECTIONS HAVE BEEN COMPLETED. ACCEPTANCE AND APPROVAL BY AN INSPECTOR OF THIS DEPARTMENT IS REQUIRED AND MUST BE CORRECTED

FIELD CORRECTION NOTICE

LOCATION 1320 W. RIVERVIEW PERMIT NO. 01722

ISSUED TO LYNN RAUSCH
PERMIT HOLDER AND/OR ALL RESPONSIBLE PARTIES.

NOTICE DELIVERED TO LYNN RAUSCH 718 STRONG

Upon inspection, violations of the C.A.B.D. Sec. _____ were in evidence.

The following orders are hereby issued for their correction:

③ PROVIDE A/D EXHAUST FAN FOR THE BASEMENT

1/2 BATH not comp. 1/19

PLEASE CALL FOR INSPECTION WHEN CORRECTIONS HAVE BEEN COMPLETED. ACCEPTANCE AND APPROVAL BY AN INSPECTOR OF THIS DEPARTMENT IS REQUIRED AND MUST BE CORRECTED

ON OR BEFORE _____

FIELD CORRECTION NOTICE

LOCATION 1320 W. RIVERVIEW PERMIT NO. 01722

ISSUED TO LIPOO BANCH PERMIT HOLDER AND/OR ALL RESPONSIBLE PARTIES.

NOTICE DELIVERED TO LIPOO BANCH 716 STROUNG

Upon inspection, violations of the CADILLAC Sec. were in evidence.

The following orders are hereby issued for their correction:

① PROVIDE THE EVIDENT FOR THE DEPARTMENT

112 DATA NOT COMP. 11/9

PLEASE CALL FOR INSPECTION WHEN CORRECTIONS HAVE BEEN COMPLETED. ACCEPTANCE AND APPROVAL BY AN INSPECTOR OF THIS DEPARTMENT IS REQUIRED AND MUST BE CORRECTED

ON OR BEFORE _____