

P E R M I T

CITY OF NAPOLEON
255 W. RIVERVIEW AVE
NAPOLEON, OHIO 43545

DIVISION OF BUILDING & ZONING
PH (419) 592-4010
FAX (419) 599-8393

PERMIT NO: 99280 DATE ISSUED: 08-10-99 ISSUED BY: BND

JOB LOCATION: 856 W RIVERVIEW AVE EST. COST:

LOT #: SUBDIVISION NAME:

OWNER: CHURCH OF THE NAZARENE
ADDRESS: 630 APPIAN AVE
CSZ: NAPOLEON, OH 43545
PHONE: 419-592-1586

AGENT: RUPP ROSEBROCK INC
ADDRESS: 7464 US HWY 24
CSZ: LIBERTY CENTER, OH 435
PHONE: 419-533-7999

USE TYPE - RESIDENTIAL: OTHER:

ZONING INFORMATION

DIST: LOT DIM: AREA: FYRD: SYRD: RYRD:
MAX HT: # PKG SPACES: # LOADING SP: MAX LOT COV:

BOARD OF ZONING APPEALS:

WORK TYPE - NEW: REPLMNT: ADD'N: ALTER: REMODEL:

WORK INFORMATION

SIZE - LGTH: WIDTH: STORIES: LIVING AREA SF:
GARAGE AREA SF: HEIGHT: BLDG VOL DEMO PERMIT:

WORK DESCRIPTION

ADDITION TO CHURCH
PER APPROVED PLANS

Footer + foundation only!

FEE DESCRIPTION

PAID DATE

FEE AMOUNT DUE


ZONING PERMIT 25.00
SITE UTILITIES INSPEC 50.00

TOTAL FEES DUE 75.00

DATE

APPLICANT SIGNATURE

Zoning Permit Only!
other permits may be required



12/16/98 - 856 W. Riverview Ave. Napoleon, Ohio detached garage

Robert P. May Custom Concrete - footer & foundation contractor.

Talked to Mr. May at around 3PM 12/16/98, he had poured the footer and foundation for the subject garage just a few hours prior to our conversation. I explained to him that the weather forecast stated that the low temp was going to be in the low 20's. He said that the concrete had enough heat in it and that he had heard it was only going to be in the 30's. I told him he should cover the fresh concrete with insulation blankets or straw. He proceeded to tell me how straw would discolor the concrete and that he did not own concrete insulating blankets. Mr. May left the concrete uncovered (the temperature went into the low 20's that night. As of 4pm 12/17/98 all the concrete that was poured at 856 W. Riverview Ave. was still not covered. He poured an approach slab along the north side of the garage on 12/17/98 am and did not cover it either. Talked to Jerry Clum of Bullock Garages (the building contractor) at 3:45PM regarding contractor registration, I also explained in him that Mr. May had not covered the concrete at all and I had serious concerns regarding the concrete freezing and not fully curing. He said he would talk to Mr. May. Mr. Clum explained that if there was a problem with the concrete later on that Mr. May would replace it.