



1441

1445

4" clo

4" clo

4" PVC DWV
sewer
existing

95.7'

22° ell

6" PVC to VIT
extension

Fire Hydrant

6" VIT
sewer service

Intercept
grease trap

4" inspection
outlet

4" sewer line
to bathroom

6" clo SDR35 PVC
@ 3.2' F/L

620

1431

620

1431

620

1431