


1013 STEVENSON STREET



Investigation of illegal sewer connections revealed three (3) illegal connections. All downspouts have been corrected and all are in compliance at this time.

SCANNED