



Investigation of illegal sewer connections revealed two (2) illegal connections. All downspouts have been corrected and are in compliance at this time.

1065 STEVENSON STREET

N
1' = 20'

1015

1065

1057

STEVENSON STREET
30

PUGHED & CEMENTED AT GRADE (IN CONC.)

OUTLETS THROUGH BRICK LANDSCAPING