

City of Napoleon, Ohio

Engineering Department

255 West Riverview Avenue, P.O. Box 151
Napoleon, OH 43545
Chad E. Lulfs, P.E., P.S., Director of Public Works
Telephone: (419) 592-4010 Fax: (419) 599-8393
www.napoleonohio.com

Tyler Swary 748 Strong Street Napoleon, OH 43545

Dear Mr. Swary,

At your request, here is a copy of our Haley Interceptor Sewer I/I study report from 2006. This shows at the address 748 Strong Street that when smoke and dye testing was conducted on the City's sanitary sewers that the "left side eaves smoked". As a result, a letter was sent to Rachel Clapp dated April 13, 2015, stating that a potential illegal sewer connection has been indicated on the property. Clapp contacted the City and I conducted a second field investigation for the alleged illegal connection. In finding that the sump pump was correctly discharging to the storm sewer and none of the downspouts were in violation, there were no illegal sewer connections causing the eaves to smoke. I advised Clapp that she may want to have her indoor plumbing checked to make sure that there were no pipe leaks that would have allowed the smoke to fill the attic and exit through the eaves. The investigation of illegal sewer connections by the City was concluded at that time on April 16, 2015.

Sincerely,

Martin T. Crossland, E.I.

Staff Engineer City of Napoleon

255 West Riverview Avenue

Napoleon, OH 43512



COMPLETED		ADDRESS	NOTES
			HALEY AVE LOCATIONS
	515	Avon Place	dyed positive to SAN MH south of residence
	707	Erie Street	right side front and back downspouts smoked
	728	Erie Street	left back downspout smoked; cleanout smoked
	231	Garden Court	
	903	Haley Avenue	front downspouts smoked (one in use and the other not in use)
	914	Haley Avenue	back middle downspout smoked; downspout not into ground foundation in front smoked; basement in back smoked; back downspou
	915	Haley Avenue	smoked porch smoked
	939	Haley Avenue	foundation on left side smoked
	505	High Street	front right and left downspouts smoked; right side downspout smoked; left side downspout smoked
	517	High Street	back left side downspout smoked
	526	High Street	front right side downspout smoked
	533	High Street	back right side downspout smoked (not in use)
	612	Leonard Street	dyed positive to SAN MH
	615	Leonard Street	front right and left downspouts smoked
	639	Leonard Street	right side of house smoked
	641	Leonard Street	dyed positive to SAN MH
	920	Lumbard Street	back left side corner of foundation smoked
	924	Lumbard Street	front right side foundation smoked
	210	Nanta a A	dyed positive to SAN H-17 for northwest corner d/s;
	313	Norton Avenue	southwest corner d/s clogged & s/p unconnected
	614	Norton Avenue	dyed positive to SAN H-31
	825	Norton Avenue	right side and back downspouts smoked; 2' x 2' drain in garage smoked
	827	Norton Avenue	dyed positive to SAN MH
	639	Park Street	front and back downspout smoked (not in use); cleanout smoked
	642	Park Street	right side downspout smoked (not in use)
	651	Park Street	back downspouts smoked
	735	Park Street	back downspout smoked (not in use); front right foundation smoked; cleanout smoked
	750	Park Street	right front downspout smoked (not in use); cleanout smoked
	715	Romain Avenue	floor drain and garage smoked
	303	Sheffield Avenue	left front downspout smoked (not in use)
	305	Sheffield Avenue	back downspout smoked
	631	Strong Street	front left foundation smoked
	702	Strong Street	yard smoked
	705	Strong Street	basement smoked from sump pump
	707	Strong Street	left front downspout smoked
	730	Strong Street	left front downspouts smoked; both back corner downspouts smoked (not in use)
	737	Strong Street	back downspout smoked
	742	Strong Street	front downspouts smoked; back downspout smoked (not in use)
	748	Strong Street	left side eaves smoked
	749	Strong Street	front downspouts smoked (not in use)
	221	W Clinton Street	front left side downspout smoked
	403	W Clinton Street	front left side yard smoked
	415	W Clinton Street	back right side yard smoked
	431	W Clinton Street	chimney smoked
	432	W Clinton Street	back downspouts smoked
	505	W Clinton Street	right side downspout smoked