



1459 TAYLOR DRIVE

2015



SCANNED
N
1"=20'

TAYLOR DRIVE



Investigation of illegal sewer connections revealed five (5) illegal connections. All downspouts have been corrected and are in compliance at this time.

