


621 TRAIL DRIVE

2015



Investigation of illegal sewer connections revealed four (4) illegal connections. All downspouts have been corrected and are in compliance at this time.

SCANNED