DATE: 10-9-12 INSPECTED BY: MARTY CROSSLAND WEST WASHINGTON STREET 1=20 231

INVESTIGATION OF LLEGAL DOWNSPOUT CONNECTIONS AT 231 W. WASHINGTON ST. WORK DONE EARLIER IN ZOIZ SEPARATED 4 BYPASSED EXISTING SANTIARLY THROM THE SOUTHEAST CORNER OF THE HOUSE TO THE STREET. ALL REMAINING FOOTER TILES 4 DOWNSPOUT CONNECTIONS GO TO SUMP PIT IN BASEMENT AND OUTLETS ON GROUND SURPACE IN FRONT OF HOUSE. THEREFORE THE EXISTING CONNECTIONS ARE EXEMPT 4 COMPLY.