



W. WASHINGTON ST.

411

409

403

ReRouted  
ok

9-27-12

INSPECTED BY: MARTY  
CROSSLAND

FOLLOW-UP INVESTIGATION OF  
ILLEGAL DOWNSPOUT CONNECTIONS  
AT 409 W. WASHINGTON ST.  
FOUND ALL TO BE IN COMPLIANCE  
AT THIS TIME.

N  
1"=20'