

City of NAPOLEON,

255 WEST RIVERVIEW AVENUE, P.O. BOX 151 NAPOLEON, OHIO 43545-0151 (419) 592-4010 FAX (419) 599-8393

ugust 07, 1996

Mayor Donald M. Stange Mr. Steven Kloos 1166 Westchester Napoleon, Ohio 43545

Members of Council Michael J. DeWit. President Sarah J. Peper John E. Church James Hershberger Terri A. Williams Travis B. Sheaffer Dennis Fligor

Re. Garage foundation walls

Dear Steve

I met with Roger Miller of Miller Construction (they placed your footings) and Neil Mock regarding your garage floor and foundation wall movement.

City Manager Marc S. Gerken, P.E.

Finance Director Gregory J. Heath

Law Director David M. Grahn

City Engineer Adam C. Hoff, P.E.

I believe what has occurred is that the garage floor raised when the ground below it froze and because the garage floor was bonded to the first row of concrete block this caused that row to shift and crack in various locations. Also I believe what may have compounded the situation was that the foundation and the underside of the garage slab where exposed to excessive moisture due to the lack of proper drainage.

The only way that I can see to eliminate the raised garage floor is to remove it and place new. I would also suggest placing a footer tile along the north & east sides of the garage foundation walls. It is always best to have good drainage as it will increase the life of the foundation walls.

If you have questions or concerns please call me at 592-4010.

Sincerely

Brent N Damman **Building & Zoning** Administrator

CC. Mr. Neil Mock, Mock/Buehrer Builders Mr. Roger Miller, Miller Construction

DOC\BUILDING\1166WTCH.SAM

Mr. Neil Mock Mock/Buehrer Builders 1227 Dodd St. Napoleon, Ohio 43545

Mr. Roger Miller Miller Construction 10-036 County Rd. X Archbold, Ohio 43502