


1"=20'

11-30-2022

J. Hillis

Imp. By: A. Debl



Installed 6" cleanout on existing PVC lateral to clean + camera.

421

Brownell