

CITY OF NAPOLEON
 Engineering Department
 255 Riverview Avenue
 NAPOLEON, OHIO 43545

DATE	March 4, 1976		JOB NO.	--
PROJECT	@ Present Mercantile BB-67 of O.B.C.			
LOCATION	120 East Clinton Street			
CONTRACTOR	--	OWNER	Fleck	
WEATHER	--	TEMP.	-- °at	AM
			-- °at	PM
PRESENT AT SITE	Tom Terranova - Building Insp.			
	Norman Howes - Electrical Insp.			
	Mr. Bill Oberhaus - Mgr.			

TO Fleck Food Store
120 East Clinton Street
Napoleon, Ohio 43545

THE FOLLOWING WAS NOTED: during requested building survey:

1) Both front and rear exits require illuminated exit sign and directional sign (for rear only). Type A, B or D exit signs. Section BB-67-18 of O.B.C.

2) Self closing devices required for both toilet rooms and directional signs to toilet rooms for general public use. Section BB-67-23.

3) Front exit door requires permanent-type sign, in clear lettering not less than one eighth of an inch in height and reading "The opening of this door from this side shall not require the use of a key during business hours." Section BB-67-13.

COPIES TO William D. Oberhaus

FIELD REPORT

SIGNED

Thomas W. Terranova

CITY OF NAPOLEON

Engineering Department

ELECTRICAL INSPECTION FIELD REPORT

255 Riverview Avenue Napoleon, Ohio 43545

(Please Print or Type)

Project Name Fleck Food Store

Address 120 East Clinton Street

City Napoleon State Ohio

Approved

Violation X

Electrical Contractor

Remarks:

Code Reference

1. Absence of adequate grounding of service equipment.	N.E.C. 75' Edition 250-81
2. Absence of adequate bonding of service equipment.	250-72(d)
3. Absence of adequate grounding of general equipment.	250-42
4. Absence of adequate grounding of specific equipment.	250-43
5. Absence of adequate grounding of cord connected equipment.	250-45
6. Disconnect and circuit breaker enclosures used as raceways, and splice boxes.	373-8
7. Insulating bushings to be used where conductors enter raceway box or cabinets.	373-6(c)
8. Locknuts to be used under insulating bushings.	373-6(c)
9. Junction boxes and wire ways not sized properly.	370-6b & 370-18
10. Raceways not supported adequately.	348-12
11. Covers missing.	370-18 3 (c)
12. Unused openings not sealed.	370-8

Compliance Time

Inspectors Signature *Norman Hous*

Copies To: William D. Oberhaus

White - Applicant Yellow - Engineering Pink - Electrical Inspector

Date March 4, 1976

Permit No. --

Type of Inspection Requested Electrical Survey @ Present Mercantile

Type of Occupancy BB-67 of O.B.C.

8/14/76

NORTHWESTERN OHIO COMMUNITY

ACTION COMMITTEE

MRS. CHARLOTTE WANGRIN

PHONE NO. 592-4706

COORDINATOR MIKE GALBRAITH

OFFICE NO. 782-3233

OR 784-2150

RE: NEED LETTER FROM BLDG. COMM.

4 FIRE INSPECTOR INDICATING

FLECK SUPER MARKET CORNER

OF CLINTON + MONROE OK

ZONING 4 STRUCTURAL FOR

PROPOSED COMMUNITY

CENTER FOR ELDERLY

FOR \$50,000 GRANT (FEDERAL GRANT THROUGH
OHIO OFFICE ON AGING.)

SEND COPY TO: MRS. WANGRIN

HENRY COUNTY SENIOR CENTER
OF NAPOLEON, OHIO

To: Building zoning Inspector
Tom Ferraroda

Building and Electrical Interview Inspection

I hereby authorize the above
mentioned to conduct an on the premises
inspection of the Fleck Food Store

William D. Obenaus
Mgt.

3/4/76

RECEIVED

MAR 4 1976

CITY OF NAPOLEON
ENGINEERING DEPT.

BY: *[Signature]*