DATE: 10-9-12 INSPECTED BY: MARTH CROSSLAND INVESTIGATION OF ILLEGAL DOWNSPOUT CONNECTIONS AT 426 W. CLINTON ST. ONE CONNECTION IN QUESTION WAS FOUND TO DUTLET ON THE GROUND SURFACE AT THE REAR OF THE PROPERTY. 1=20' TO REAR OF PROPERTY WEST CHATON STREET