

West Clinton



505

509

515

DATE: 6-28-12  
INSPECTED BY: MARTY CROSSLAND  
INVESTIGATION OF ILLEGAL DOWNSPOUT  
CONNECTION AT 509 W. CLINTON ST.  
ALL DOWNSPOUTS WERE FOUND TO BE  
DISCONNECTED AND IN COMPLIANCE.

1"=20'

SCANNED

