

WEST CLINTON STREET



515

523

W. CLINTON ST.

29



DATE: 10-8-12  
INSPECTED BY: MARTY CROSSLAND  
INVESTIGATION OF ILLEGAL  
DOWNSPOUT CONNECTIONS  
AT 523 W. CLINTON ST.  
ONE CONNECTION HAS BEEN  
DISCONNECTED AND CAPPED  
OFF. NO OTHER CONNECTIONS  
SEEN AT THIS TIME.

1"=20'