

Date: February 21-1977

TO: The Building Inspector - Engineering Dept.

FROM: Electric Distribution Superintendent

Confirmed the installation of 4/100 AMP. electrical
service entrance, located Rear of Addition

at the following address: 1051 Doved Street

Approved Not Approved _____

K. Change 2 21 77
Electric Supt. Date

Remarks: Talked to Dan & he'll pay slipper - and Put heavy sliders
↓ Bolt for me.

Date: 2-21-77

TO: Electric Distribution Superintendent

FROM: The Building Inspector - Building Department

Please confirm the installation of 4-100 AMP. electrical service entrance's located REAR OF ADDITION IN THE CENTER

at the following address: 1051 DODD ST.

Approved _____

Not Approved

K. Chang
Electric Supt.

2-21-77

Date

Remarks: We'll run service drop to Northwest rear of Building only. Not possible to hit rear of Building center.

See 2-21-77 for much you