

P E R M I T

CITY OF NAPOLEON  
255 W. RIVERVIEW AVE  
NAPOLEON, OHIO 43545

DIVISION OF BUILDING & ZONING  
PH (419) 592-4010  
FAX (419) 599-8393

PERMIT NO: 896                      DATE ISSUED: 11-09-01                      ISSUED BY: SKE  
JOB LOCATION: 431 FILLMORE ST                      EST. COST: 2499.00

LOT #:                      SUBDIVISION NAME:

OWNER: APT, RANDY                      AGENT: QUILLAN BROS INC.  
ADDRESS: 431 FILLMORE ST                      ADDRESS: 06902 US 27  
CSZ: NAPOLEON, OH 43545                      CSZ: BRYAN, OH 43506  
PHONE: 419-592-0871                      PHONE: 419-636-1303

USE TYPE - RESIDENTIAL:                      OTHER:

ZONING INFORMATION

DIST:                      LOT DIM:                      AREA:                      FYRD:                      SYRD:                      RYRD:  
MAX HT:                      # PKG SPACES:                      # LOADING SP:                      MAX LOT COV:

BOARD OF ZONING APPEALS:


WORK TYPE - NEW:                      REPLMNT: X                      ADD'N:                      ALTER:                      REMODEL:

WORK INFORMATION

SIZE - LGTH:                      WIDTH:                      STORIES:                      LIVING AREA SF:  
GARAGE AREA SF:                      HEIGHT:                      BLDG VOL DEMO PERMIT:

WORK DESCRIPTION  
REPL WINDOWS

FEE DESCRIPTION	PAID DATE	FEE AMOUNT DUE
BUILDING PERMIT		27.00



TOTAL FEES DUE 27.00

11-9-01  
-----  
DATE

*John B...*  
-----  
APPLICANT SIGNATURE

CITY OF NAPOLEON INSPECTION FORM

PERMIT #: 896

DATE ISSUED: 11-09-2001

JOB LOCATION: 431 FILLMORE ST

OWNER: APT, RANDY

OWNER PHONE: 419-592-0871

CONTRACTOR: QUILLAN BROS INC.

CONTRACTOR PHONE: 419-636-1303

WORK DESCRIPTION: REPL WINDOWS

PLUMBING:   UNDGR \_\_\_\_\_ RGHIN \_\_\_\_\_ FINAL \_\_\_\_\_

          SEWER INSP \_\_\_\_\_

MECHANICAL: UNDGR \_\_\_\_\_ RGHIN \_\_\_\_\_ FINAL \_\_\_\_\_

          FURNACE REPLC \_\_\_\_\_ AIR COND \_\_\_\_\_

ELECTRICAL: UNDGR \_\_\_\_\_ RGHIN \_\_\_\_\_ FINAL \_\_\_\_\_

          SERV UPGR \_\_\_\_\_

BUILDING:   SITE \_\_\_\_\_ FTG \_\_\_\_\_ FNDDT \_\_\_\_\_

          STRUC \_\_\_\_\_ ROOF \_\_\_\_\_ EXT \_\_\_\_\_

          VENT \_\_\_\_\_ ACCES \_\_\_\_\_ EGRS \_\_\_\_\_

          SMKDT \_\_\_\_\_ FINAL \_\_\_\_\_

          ISSUE TEMP OCCUP \_\_\_\_\_ ISSUE OCCUP \_\_\_\_\_

STRG SHED: SITE \_\_\_\_\_ FINAL \_\_\_\_\_

SIGN:       FTG \_\_\_\_\_ FINAL \_\_\_\_\_

FENCE:     SITE \_\_\_\_\_ FINAL \_\_\_\_\_

MISC INSP: 11-16-01 \_\_\_\_\_

NOTES: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

INSPECTOR INITIALS: \_\_\_\_\_