

**CITY OF NAPOLEON  
BUILDING CONSTRUCTION PERMIT  
(1, 2 or 3 Family Dwelling)**

Permit No. 143-74  
 Issued 9/25/74  
 By Ronald W. Brown  
 Building Inspector

Valuation \$1,500

Fees	Base	Plus	Total
Construction	\$6.00	—	\$6.00
Plumbing			
Electrical			
Heating			
Water Tap			
Sewer Tap			
Temporary Elec.			
<b>TOTAL</b>	<b>\$6.00</b>	<b>—</b>	<b>\$6.00</b>

Owner Name Gail Sloan  
 Address 233 East Front St.  
 Builder Name Self  
 Address \_\_\_\_\_ Tel. 592-0591

**Lot Information:**

Street No. 233 East Front St.  
 Lot Between 819 Subdivision Original Plat  
 Lot Dimensions \_\_\_\_\_ Lot Area \_\_\_\_\_ Sq. Ft.  
 Yard Set Back: Front \_\_\_\_\_ Rear \_\_\_\_\_  
 Side \_\_\_\_\_ Side \_\_\_\_\_

Zoning "EP" Intended use of Building: Repairing existing roof system and re-building rafters, to install new sheathing and roof shingles.

**Building Information:**

Single  Double \_\_\_\_\_ Multiple \_\_\_\_\_ New Construction \_\_\_\_\_ Addition \_\_\_\_\_ Remodel   
 Size: Length \_\_\_\_\_ Width \_\_\_\_\_ No. of Stories \_\_\_\_\_  
 Floor Area: 1st Floor \_\_\_\_\_ 2nd Floor \_\_\_\_\_ 3rd Floor \_\_\_\_\_ Basement \_\_\_\_\_  
 Unfinished Attic \_\_\_\_\_ Garage \_\_\_\_\_  
 Foundation: Piers \_\_\_\_\_ Full Basement \_\_\_\_\_ Part Basement \_\_\_\_\_  
 Concrete \_\_\_\_\_ Block \_\_\_\_\_  
 Walls: Frame \_\_\_\_\_ Block \_\_\_\_\_ Brick \_\_\_\_\_ Other \_\_\_\_\_  
 Electrical: Wiring \_\_\_\_\_ Electric Heating \_\_\_\_\_ Electrical Appliances \_\_\_\_\_  
 Plumbing: Fixtures or Traps \_\_\_\_\_ Warm Air Heating \_\_\_\_\_ Hot Water Heating \_\_\_\_\_  
 Additional Information: Under 15 lbs. building required under new roofing shingles.  
paper

Date 9-25-74 Applicant Signature Gail T. Sloan  
 Owner - Builder - Agent

THIS PERMIT FOR THE CONSTRUCTION OF A NEW ROOF ONLY.

**Inspection Record:**

Work Started \_\_\_\_\_ Foundations \_\_\_\_\_ Plumbing, Heating \_\_\_\_\_  
 Set Back, Side Lines \_\_\_\_\_ Plumbing (Rough In) \_\_\_\_\_ And Air Conditioning \_\_\_\_\_  
 Excavation \_\_\_\_\_ Erecting Frame \_\_\_\_\_ Roof \_\_\_\_\_  
 Footing \_\_\_\_\_ Electrical Work \_\_\_\_\_

Comments: \_\_\_\_\_

Certificate of Occupancy Issued \_\_\_\_\_ Inspector \_\_\_\_\_