City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Ada Business Na	dress: 2400 me: 61en A	o Glei	n Arbors	or 6ldg.	ZIP: 43545			
Type (circle		DC	NFORMATIO VB	RPD				
Location of I	Device: <u>by</u>	Gauge	ter	Serial No	35819			
Outlet valve	Reduced Pre			Pressure Vacuum Breaker				
holding RP⊠ DC□	Double Check Valve ↓		Relief Valve	Air Inlet	Check Valve			
failed RP□ DC□	1st Check	2nd Check	Ų.	-				
Test Results	DCpsi	DCpsi	opened at 2.8 psi	opened atpsi	held atpsi			
Yaz	RP_ 7.1 psi		did not open □	did not open	leaked [
Date: 4-24-12	Pass В Failed □	Pass ☐ Failed ☐	Pass Failed	Pass □ Failed □	Pass □ Failed □			
Repairs & Materials			EF.					
Test After	DCpsi	DCpsi	opened atpsi	opened atpsi	held at psi			
Repairs	RPpsi	RPpsi	did not open □	did not open □	leaked [
Date:	Pass □ Failed - □	Pass [] Failed []	Pass □ Failed □	Pass	Pass □ Failed □			
Tester Signature: Certification No. Certification No.								

Customer - Pink

Tester - Goldenrod

Building Dept. - Canary

Water Dist. - White

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Type (circle		DC	NFORMATIC VB	RPD	
Location of	Device: by	M2 OT Water me	ter	Serial No	3777/
Outlet valve	Reduced Pro			Pressure Vacuum Breaker	
holding RP DC	Double Chec	ck Valve	Relief Valve	Air Inlet	Check Valv
failed RP DC	1st Check	2nd Check	t)		×
Test Results	DCpsi RP 9.2 psi	DCpsi	opened at 2.8 psi	opened atpsi	held at
			did not open □	did not open □	leaked [
Date: 4-24-02	Pass Failed	Pass Failed □	Pass Failed	Pass Failed	Pass Failed
Repairs & Materials	5				
Test After Repairs	DCpsi RPpsi	DCpsi RPpsi	opened at psi did not open	opened at psi did not open	held at psi
Date:	Pass □ Failed □	Pass □ Failed □	Pass □ Failed □	Pass □ Failed □	Pass □ Failed □