

95 GLENBROOK COURT
ILLEGAL DOWNSPOUT INVESTIGATION

W.M.

GL HARMONY DRIVE

8" San.

2916

1" N
1' = 20'

ALL ILLEGAL CONNECTIONS
HAVE BEEN CAPPED OR PLUGGED
AND ARE IN COMPLIANCE AT
THIS TIME.

INSPECTED BY: MARK SPIESS

CAPPED CONCRETE
BELOW GRADE

EX. C/O

XOK

XOK

95

XOK

XOK

XOK

W.M.

Glenbrook Crt.

