

4-20-92

Paul Walters

8" Vit cleanout cleaned of roots,  
lower portion broken down  
needs replaced.

Sonny Helbing

828

West Raceway

824

6" P.V.C. Cleanout



4 ft deep

1 1/2"

3 1/2"



8" Vit cleanout 8" underground  
6 ft deep

Cross in curb

