

2015

1" = 20'

305 NORTH HARMONY DRIVE  
ILLEGAL DOWNSPOUT INVESTIGATION

NORTH HARMONY DRIVE

305

32

CAPPED & CEMENTED BELOW GRADE

CAPPED + CONCRETED BELOW GRADE

ALL ILLEGAL CONNECTIONS HAVE BEEN CAPPED OR PLUGGED AND ARE IN COMPLIANCE AT THIS TIME.  
INSPECTED BY: MARK SPIESS

