X<sub>o</sub>

180 HARMONY DRIVE

HARMONY DRIVE

Investigation of illegal sewer connections revealed four (4) illegal connections. All downspouts have been corrected and are in compliance at this time.

A CAPPED \*
CEMENTED \*
SEGUED ATT SEGUED
ATT SEGUED
ATT SEGUED

CAPPED +
CEMENTED
BELLOW SPLANE