

1145 Highland

5-20-92

Jerry Glanz

Paul Valters

Repair + Replace 4" Sch 20 pvc with
6" PVC SDR Sch 35.

