

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1253 Independence DRIVE ZIP: 43545
 Business Name: UNIVERSAL COOPERATIVE Inc

DEVICE INFORMATION

Type (circle one) **RP** DC VB RPDA DCDA
 Manf/Model: WATIS 909 Size: 3 Serial No. 153790
 Location of Device: WATER METE SETTING
 Type of Test: Differential Gauge Sight Tube

Outlet valve holding RP <input type="checkbox"/> DC <input type="checkbox"/> failed RP <input type="checkbox"/> DC <input type="checkbox"/>	Reduced Pressure <input checked="" type="checkbox"/> Assembly ↓ Double Check Valve ↓ 1st Check 2nd Check			Pressure Vacuum Breaker Air Inlet Check Valve	
				Relief Valve ↓	
	Test Results	DC _____ psi RP <u>8.4</u> psi	DC _____ psi	opened at <u>2.6</u> psi did not open <input type="checkbox"/>	opened at _____ psi did not open <input type="checkbox"/>
Date: <u>9.3.03</u>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi RP _____ psi	DC _____ psi RP _____ psi	opened at _____ psi did not open <input type="checkbox"/>	opened at _____ psi did not open <input type="checkbox"/>	held at _____ psi leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Daniel R Brown Certification No. 528
 Owner/Representative Signature: Richard Steele