

# City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 460 2nd Zip: 43545  
 Business Name: Napoleon Car Wash  
 Contact Person: Ken Hoge Title: Owner  
 Phone Number: 599-2215 Date of Test: June 26, 1998  
Home 278-6345

### DEVICE INFORMATION

Type (circle one) RP DC VB RPDA DCDA  
 Manf/Model: Watts 909 Size: 1 1/2 Serial No.: 314300  
 Location of Device: North East Corner Mech Room

Type of Test: Differential Gauge  Sight Tube

Outlet Valve Holding <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Reduced Pressure Assembly		Pressure Vacuum Breaker		
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Test Results	DC _____ psi <u>Apparent RP 5.2 psi</u> <u>Actual RP _____ psi</u>	DC _____ psi <u>8</u>	Opened at <u>3.4</u> psi  Did Not Open <input type="checkbox"/>	Opened at _____ psi  Did Not Open <input type="checkbox"/>	Held at _____ psi  Leaked <input type="checkbox"/>
Date:	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi  RP _____ psi	DC _____ psi  RP _____ psi	Opened At _____ psi  Did Not Open <input type="checkbox"/>	Opened At _____ psi  Did Not Open <input type="checkbox"/>	Held At _____ psi  Leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Brian Tjell Certification No. 611  
 Owner/Representative Signature: Jeffrey C. Maudugh