

# City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1675 Industrial Dr. Zip: 43545  
 Business Name: Carson Industries  
 Contact Person: Brian Ramey Title: Maint. Manager  
 Phone Number: 592-2309 Date of Test: 8-31-00

### DEVICE INFORMATION

Type (circle one) RP DC VB RPDA DCDA  
 Manf/Model: Conbraco HC070 Size: 1" Serial No.: 4010582  
 Location of Device: in furnace room old Bldg.

Type of Test: Differential Gauge  Sight Tube

Outlet Valve	Reduced Pressure Assembly		Pressure Vacuum Breaker		
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
Holding <input checked="" type="checkbox"/>	1st Check	2nd Check			
Failed <input type="checkbox"/>					
Test Results <u>Pass</u>	DC <u>10</u> psi	DC <u>10</u> psi	Opened at _____ psi	Opened at _____ psi	Held at _____ psi
	<u>Apparent</u> RP _____ psi		Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
	<u>Actual</u> RP _____ psi		Pass <input type="checkbox"/>	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>
Date: <u>8-31-00</u>	Pass <input checked="" type="checkbox"/>	Pass <input checked="" type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi	DC _____ psi	Opened At _____ psi	Opened At _____ psi	Held At _____ psi
	RP _____ psi	RP _____ psi	Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>
	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>

Tester Signature: Vincent J. Bata Certification No. 432<sup>th</sup>  
 Owner/Representative Signature: Brian Ramey

# City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1675 Industrial Dr Zip: 43595  
 Business Name: Carson Industries  
 Contact Person: Brian Ramsey Title: Plant Manager  
 Phone Number: 592-2309 Date of Test: 8-3-00

### DEVICE INFORMATION

Type (circle one)      RP      **DC**      VB      RPDA      DCDA  
 Manf/Model: Conbraco ALS03      Size: 1"      Serial No.: 40105A2T  
 Location of Device: Near Sprinkler main  
 Type of Test:      Differential Gauge       Sight Tube

Outlet Valve	Reduced Pressure Assembly		Pressure Vacuum Breaker		
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Holding <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	DC <u>10</u> psi	DC _____ psi	Opened at _____ psi	Opened at _____ psi	Held at _____ psi
Test Results <u>Pass</u>	<u>Apparent</u> RP _____ psi		Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
Date: <u>8-31-00</u>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi	DC _____ psi	Opened At _____ psi	Opened At _____ psi	Held At _____ psi
	RP _____ psi	RP _____ psi	Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
te:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Signature: Vincent A. B... Certification No. 432#  
 Representative Signature: Brian Ramsey



# City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1675 Industrial Dr. Zip: 43545  
 Business Name: Carson Industries  
 Contact Person: Brian Ramey Title: Maint. Manager  
 Phone Number: 592-2309 Date of Test: 8-31-00

### DEVICE INFORMATION

Type (circle one) **RP** DC VB RPDA DCDA  
 Manf/Model: Watts 009 m2 Size: 3/4" Serial No.: 37122  
 Location of Device: near sprinkler main

Type of Test: Differential Gauge  Sight Tube

Outlet Valve Holding <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Reduced Pressure Assembly		Pressure Vacuum Breaker		
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Test Results: <b>Pass</b>	DC _____ psi	DC _____ psi	Opened at <u>4.5</u> psi	Opened at _____ psi	Held at _____ psi
	<u>Apparent</u> RP <u>7.25</u> psi		Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
	<u>Actual</u> RP <u>7.0</u> psi		Pass <input type="checkbox"/>	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>
Date: <u>8-31-00</u>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi	DC _____ psi	Opened At _____ psi	Opened At _____ psi	Held At _____ psi
	RP _____ psi	RP _____ psi	Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: [Signature] Certification No. 43271  
 Owner/Representative Signature: [Signature]

# City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1675 Industrial Zip: 43545  
 Business Name: Lawson Industries  
 Contact Person: Brian Ramey Title: Plant Manager  
 Phone Number: 419-592-2309 Date of Test: Aug 30, 00

### DEVICE INFORMATION

Type (circle one)      **RP**      **DC**      **VB**      **RPDA**      **DCDA**  
 Manf/Model: Fulco 9054D Size: 8" Serial No.: 9502091420  
 Location of Device: S.E. Corner by Maintenance Shop  
 Type of Test:      Differential Gauge       Sight Tube

Outlet Valve	Reduced Pressure Assembly		Pressure Vacuum Breaker		
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
Holding <input checked="" type="checkbox"/>	1st Check	2nd Check			
Test Results: <b>Fail</b> Date: <b>4-30-00</b>	DC _____ psi <u>Apparent</u> RP _____ psi <u>Actual</u> RP _____ psi Pass <input type="checkbox"/> Failed <input checked="" type="checkbox"/>	DC _____ psi Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Opened at _____ psi Did Not Open <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Opened at _____ psi Did Not Open <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Held at _____ psi Leaked <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials	Replaced seats + O-Rings				
Test After Repairs: <b>Pass</b> Date: <b>9-18-00</b>	DC <u>10</u> psi RP _____ psi Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	DC <u>10</u> psi RP _____ psi Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Opened At _____ psi Did Not Open <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Opened At _____ psi Did Not Open <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Held At _____ psi Leaked <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Vernard J. Batt Certification No. 432  
 Owner/Representative Signature: Michael J. ...