Property Address. 1800 Supplies Zip: 43.54.5									
Business Name Contact Person: Phone Number: -117-579-50/5 Date of Test: march 20,01									
Contact Person:	Lon Fran	<u> </u>	6 -	Title: Maid	Land.				
Phone Number:	4119-599-	5015	Date of Test:	rich 20,0	1				
			FORMATION N	etu wading 2	4 W/#				
Type (circle one)	RP	DC	VB	RPDA S	(DCDA)				
Manf/Model (La	Manf/Model Size: Serial No. 3000662								
Location of Device:	los strate	<u></u>							
Type of Test:	Differential Gauge	×	Sight Tube						
Outlet	Reduced Pressure	Assembly		Pressure Vacuum E	Breaker				
Valve									
Holding X	Double Check Valv	e	Relief Valve	Air Inlet	Check Valve				
Failed	1st Check	2nd Check	4.4.5						
Test	DCpsi	DCpsi	Opened at	Opened at	Held at				
Results			psi	psi	psi				
	Apparent				7				
	RP psi								
	Actual		Did Not	Did Not	Leaked				
	RPpsi		Open	Open					
Date:	Pass	Pass 🗆	Pass 🗆	Pass 🗆	Pass 🗆				
	Failed ,	Failed □	Failed	Failed	Failed				
	Replaced Checked 1	Replaced Check#2							
Repairs &	Replace	Kebrer		-					
Materials	inck who !	Meck							
	Cher	C. 10							
			Opened At	Opened At	Held At				
Test After	DC 2.7 psi	DC 2.7 psi	psi	psi	psi				
Repairs Das 5			Did Not	Did Not	-				
ŧ.	RP psi	RP psi	Open $\square$	Open	Leaked				
Date:	Pass X	Pass 🖸	Pass	Pass	Pass				
5-8-01	Failed	Failed	Failed	Failed	Failed				
() 110 U									
Tester Signature	pud	I Jehr		Certification No.	010				
Owner/Representa	tive Signature:	in I							

Property Address:	Property Address: 1800 Industria Dr. Zip: 43545							
Business Name Courtleaf Cold storage								
Contact Person:	Ron Franz	9-11-11-11-11-11-11-11-11-11-11-11-11-11	3	Title: maint	Super.			
Phone Number:	599-5015		Date of Test:	-8-01				
		<b>DEVICE INI</b>	FORMATION					
Type (circle one)	RP	<b>6</b> C	VB	RPDA	DCDA			
Manf/Model: [5]	Ames 200	00 B	Size: 3/4	Serial No.: 043.	21			
Location of Device: South wall								
Type of Test:	Differential Gauge	18	Sight Tube					
Outlet	Reduced Pressure	Assembly		Pressure Vacuum B	reaker			
Valve								
Holding X	Double Check Valv	e	Relief Valve	Air Inlet	Check Valve			
Failed D	1st Check	2nd Check						
Test O	DC 13 psi	DC 1.3 psi	Opened at	Opened at	Held at			
Results Pass		· s	psi	psi	psi			
	Apparent			-	- 3			
Y	RP psi				T -			
4 7 3 0	Actual		Did Not	Did Not	Leaked			
1	RPpsi		Open	Open				
Date:	Pass 🔀	Pass 5	Pass 🗆	Pass	Pass 🗆			
5-8-01	Failed	Failed	Failed	Failed	Failed			
				, inspection				
Repairs &				-				
Materials								
	-				1			
			Opened At	Opened At	Held At			
Test After	DCpsi	DC psi	psi	psi	psi			
Repairs		•	Did Not	Did Not				
	RP psi	RP psi	Open	Open	Leaked			
				•				
Date:	Pass 🗆	Pass 🗆	Pass 🗆	Pass 🗆	Pass			
	Failed				Failed			
		7 /		ranou ()	A MILLS C.			
Tester Signature:	1 boul	R +	50	Certification No.	#00			
Owner/Representa	1000	- Jag		Certification No	0/0			
	orginaturo.	0	con from	7				

Property Address. 1800 Industrial Dr. Zip: 43545									
Business Name: C									
Contact Person: Re	on Franz			Title: Main. 5	Supervisor				
Phone Number:	99-5015		Date of Test:						
		DEVICE IN	FORMATION						
Type (circle one)	RP	DC	VB	RPDA	(DCDA)				
Manf/Model: Am	es 3000 55		Size: 8"	Serial No.: 3 P	00662				
Location of Device:	Location of Device: By Furnace								
Type of Test:	Differential Gauge	E .	Sight Tube						
Outlet	Reduced Pressure	Assembly		Pressure Vacuum B	reaker				
Valve	k .								
Holding <b>2</b>	Double Check Valv	e	Relief Valve	Air Inlet	Check Valve				
Failed	1st Check	2nd Check	. 1. 4 127						
7				-					
Test Pass	DC 1C psi	DC 10 psi	Opened at	Opened at	Held at				
Results 165		4	psi psi	psi	psi				
	Apparent								
	RPpsi								
	Actual		Did Not	Did Not	Leaked				
	RP psi		Open	Open					
Date:	Pass 足	Pass 4	Pass 🗆	Pass 🗆	Pass 🗆				
2-16-00	Failed	Failed	Failed	Failed	Failed				
Repairs &				and the second					
Materials									
a a									
			Opened At	Opened At	Held At				
Test After	DCpsi	DCpsi	psi	psi	psi				
Repairs			Did Not	Did Not					
	RP psi	RP psi	Open	Open	Leaked				
		•		•					
Date:	Pass 🗆	Pass 🗆	Pass 🗆	Pass	Pass				
	Failed \	Failed $\square$		Failed	Failed				
	110	- ///	7						
Tester Signature:	& piral A	Solabe	BUNGAR	Certification No.	#010				
Owner/Representa	tive Signature:	2			Company of the Compan				
- Lapi esenta	o.g.i.ataio.	in The							
AMIPRO OPERATIOBACKFLOW SAM									

#### BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address:	1165 Inde	pendence	Dr		Zip: 43545
	lover leaf	/			
Contact Person.	on Franz			Title: Main 5	upervisor
Phone Number: 5	19-5015		Date of Test:	2-16-00	
			ORMATION		
Type (circle one)	(RP)	DC	VB	RPDA	DCDA
Manf/Model: W:	Kins 975 XL		Size: 2"	Serial No.: 456	879
Location of Device	old Engin	e Kron		1911-	
	Differential Gauge		Sight Tube		
Outlet	Reduced Pressure	Assembly		Pressure Vacuum B	reaker
Valve					
Holding 🔽	Double Check Valv	e	Relief Valve	Air Inlet	Check Valve
Failed	1st Check	2nd Check	or Landberg and		10
*					
Test	DCpsi	DC psi	Opened at	Opened at	Held at
Results Pass			psi	psi	psi
	Apparent				
2.1	RP 9.6 psi				
- Ann	Actual		Did Not	Did Not	Leaked
	RP 8 psi		Open $\square$	Open	<b>)</b>
Date: 2-16-00	Pass A	Pass &	Pass 🗶	Pass 🗆	Pass 🗆
2-10	Failed	Failed	Failed	Failed 🗆	Failed
Repairs &				2	
Materials					
			E		
			Opened At	Opened At	Held At
Test After	DCpsi	DC psi	psi	psi	psi
Repairs	21		Did Not	Did Not	
	RPpsi	RP psi	Open	Open	Leaked
Date:	Pass 🗆	Pass 🗆	Pass 🗆	Pass 🗀	Pass
	Failed	Failed	Failed	Failed	Failed
-	1) 1-	01	terren en e		
Tester Signature:	aunt 3	Tepl - Dua	SAR MER	Certification No.	#010
Owner/Representa		Bon I	and of		
·					
D		0		C. AM	IPRO\OPERATIOBACKFLOW SAM

Water Dist. - White

Building Dept. - Canary Customer - Pink

Tester - Goldenrod

# Need 34" DCA on City of Napoleon

Property Address 1800 Industrial Dr. Zip: 43545									
Business Name: Cloverleaf									
Contact Person:	Ren Franz			Title: Main.	Supervisor				
Phone Number: 5	99-5015		Date of Test: 2.						
		DEVICE IN	FORMATION						
Type (circle ohe)	RP	The same of the sa		RPDA	DCDA				
Manf/Model:	Ames 2000	28	VB Size: 3/4	Serial No.: 043	21				
Location of Device: By fire System									
	Type of Test: Differential Gauge  Sight Tube								
Outlet	Reduced Pressure	Assembly		Pressure Vacuum B	reaker				
Valve									
Holding X	Double Check Valv	e	Relief Valve	Air Inlet	Check Valve				
Failed	1st Check	2nd Check							
Test	DC 10 psi	DC /O psi	Opened at	Opened at	Held at				
Results Pa55			psi	psi	psi				
	Apparent		-		•				
-	RP psi	*1							
1 . /	Actual		Did Not	Did Not	Leaked				
1	RP psi		Open	Open					
Date:	Pass 🗵	Pass 🖼	Pass 🗆	Pass	Pass 🗆				
2-16-00	Failed	Failed	Failed	Failed	Failed				
V.				5000					
Repairs &									
Materials		-							
		-							
	/								
			Opened At	Opened At	Held At				
Test After	DC psi	DC psi	psi	psi	psi				
Repairs	-	•	Did Not	Did Not	-				
	RP psi	RPpsi	Open	Open	Leaked				
		1	•						
Date:	Pass	Pass 🗆	Pass	Pass 🗆	Pass 🗆				
	Failed\	Failed			Failed				
	/ ) //				A SHAFFACE SILL				
Tester Signature:	fund B.	Lebe a	MORE MEET	Certification No.	#010				
Owner/Represent	Nº 6	Kon Thom	1/	<del>-</del>					

			Dr.		Zip: 43545	
Business Name:	Cloverlea	f				
Contact Person:	Ron France			Title: Maint.	Supervisor	
Phone Number:	599-5015		Date of Test:	1-16-00		
		DEVICE IN	FORMATION			
Type (circle one)	RP	(D)	VB	RPDA	DCDA	
Manf/Model Apr	183 2000 53	5	Size: 8"	Serial No.: 211	N 0388	
Location of Device	In pit					
	Differential Gauge		Sight Tube			
Outlet	Reduced Pressure Assembly Pressure Vacuum Breaker					
Valve						
Holding 🛛	Double Check Valv	/e	Relief Valve	Air Inlet	Check Valve	
Failed	1st Check	2nd Check				
7						
Test Pass	DC 10 psi	DC 7 psi	Opened at	Opened at	Held at	
Results		1	psi	psi	psi	
	Apparent					
	RPpsi			The same of the sa		
	Actual		Did Not	Did Not	Leaked	
	RPpsi		Open	Open		
Date: 2-16.00	Pass 2	Pass 🖽	Pass	Pass 🗆	Pass 🗆	
2-16.00	Failed	Failed	Failed	Failed	Failed	
	4			Dipoliconia and a second		
Repairs &				=		
Materials					4.	
	(+) =					
			Opened At	Opened At	Held At	
Test After	DC psi	DC psi	psi	psi	psi	
Repairs		•	Did Not	Did Not		
	RP psi	RP psi	Open	Open	Leaked	
		•	1			
Date:	Pass	Pass	Pass	Pass	Pass	
	Failed \	Failed	Failed		Failed	
		17	A TAXABLE LINE	r ontog	rance to	
Tester Signature	1 hund 6	3 John n	WERE BEEN	Contification No. 5	#010	
Owner/Representa		Street In	The state of	Certification No.		
owner/Kepresenta	ati Congnature	wr. Jang				
er Dist - White Build	ding Dont Coron	Customer Bisk Toot	on Caldania	C AM	PRO\OPERATIOBACKFLOW.SAM	

Property Address.	1165 Inda	sendence Di			Zip: 4/3545
	lover leaf				
Contact Person	Ron Franc			Title: Wain T.	Supervisor
	599-5015		Date of Test:	-16-00	/
		<b>DEVICE INF</b>	ORMATION		
Type (circle one)	RP	DC	VB	RPDA	DCDA
Manf/Model: UIK	ins 975		Size: 4"	Serial No.: 259	168
Location of Device:	New Engin	e Room			
Type of Test.			Sight Tube		
Outlet	Reduced Pressure	Assembly		Pressure Vacuum B	reaker
Valve					
Holding 💢	Double Check Valv	e	Relief Valve	Air Inlet	Check Valve
Failed	1st Check	2nd Check	a de Colores		
-3					
Test	DCpsi	DCpsi	Opened at	Opened at	Held at
Results 0155		25		psi	psi
1.	Apparent				
	RP <u>69</u> psi				
A	Actual		Did Not	Did Not	Leaked
	RP 6.2 psi		Open	Open	1 941
Date:	Pass 🔟	Pass 🙎	Pass 💢	Pass 🗆	Pass 🗆
Date:  G=111-00	Failed	Failed	Failed	Failed	Failed 🗆
	3				
Repairs &				_	
Materials		=			
	# -				
			Opened At	Opened At	Held At
Test After	DCpsi	DC psi	psi	psi	psi
Repairs			Did Not	Did Not	
	RP psi	RP psi	Open	Open	Leaked
		1			
Date:	Pass 🗆	Pass 🗆	Pass 🗆	Pass 🗆	Pass 🗆
	Failed \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Failed [] /	Failed	Failed	Failed
	110	0 11	/		
Tester Signature:	1 land	10- 1-1/h	P DUNISAR	Certification No.	4010
Owner/Representa	1 / /	Ron France	/		
		1			

Type (circle	one) RP	DEVICE II	NFORMATIC VB	<u>DN</u> RPD	A DCDA
	: Watts m Device: by A		Size:_3/4'	Serial No	83282
		l Gauge 🏋	Sight Tube		
Outlet	Reduced Pre			Pressure Vacu	um Breaker
valve	Assembly		1		
holding  RP□ DC	Double Chec	k Valve	Relief Valve	Air Inlet	Check Valve
failed	1st Check	2nd Check	₩ ¥	-	
RP DC			<b>V</b>		
Test	DC 91	DC 2.0 psi	1		
Results	DC N/A psi	DC #10 psi	opened at	opened at	held at
	77				
	RPpsi		did not	did not	Inches I
			open 🗆	open	leaked [
Date:	Pass 🛛	Pass 🗹	Pass 🗆	Pass	Pass
4-9-03	Failed	Failed	Failed	Failed	Failed
Repairs &					
Materials					*
Test After			opened at	opened at	held at
	DCpsi	DCpsi	psi	psi	psi
Repairs	RP psi	RP psi	did not	did not	
	psi	RPpsi	open 🗌	open 🗆	leaked
Date:	-				
Date.	Pass 🗆	Pass	Pass	Pass 🗆	Pass
gho may	Failed	Failed	Failed	Failed	Failed

Type (circle	one) RP	DEVICE IN	NFORMATIO VB		A DCDA
Manf/Model	Ames 20	00 B	_ Size: 3/4	Serial No	04321
Type of Test	: Differential	Gauge ki	Signi Tube	П	
Outlet	Reduced Pre			Pressure Vacu	um Breaker
valve	Assembly		1		
holding	Double Chec	k Valve	Relief	Air Inlet	Check Valve
RP DC failed	1st Check	2nd Check	<u>Valve</u>		
RP DC	1st Check	and Check	t)		
Mabou					
Test	DC 1.5 psi	DC 1.5 psi	opened at	opened at	held at
Results	+		psi	psi	ps
	RP psi		increde a direction		Exercise Sin E sine
			did not	did not	leaked [
_			open 🗌	open 🗆	*
Date:	Pass 🖺			Pass	Pass
9110)	Failed	Failed	Failed	Failed	Failed
Repairs &					
Materials					
	1				
T				1	
Test After	DC psi	DCpsi	opened at psi	opened at psi	held at psi
Repairs			did not	did not	P51
	RPpsi	RPpsi	open 🗆	open 🗆	leaked
Date:	Pass	Pass 🗆	Pass 🗆	Pass 🗆	Pass 🗆
	Failed	Failed	Failed	Failed	Failed
Tester Signat	1	I KB		tification No.	

	Property Address: 1800 Industrial Dr. ZIP: 43545 Business Name: Cloverkeaf Cold Storage							
	Type (circle one) RP DC VB RPDA DCDA							
	Manf/Model: Ames 3000 55 Size: 8" Serial No. 3 0 00 662  Location of Device: 64 Fornace  Type of Test: Differential Gauge B Sight Tube							
	Outlet valve	Reduced Pre	ssure	Sight Tube	Pressure Vacu	um Breaker		
	holding RP DC	Double Chec	k Valve	Relief Valve	Air Inlet	Check Valve		
	failed RP DC	1st Check	2nd Check	₩.				
	Test Results	DC_3,0_psi	DC 12 psi	opened atpsi	opened atpsi	held atpsi		
	E	RPpsi		did not open □	did not open □	leaked []		
	Date: 4-9-03	Pass 🗹 Failed 🗆	Pass ☑ Failed □		Pass □ Failed □	Pass   Failed		
	Repairs & Materials							
	Test After Repairs	DCpsi RPpsi	DCpsi RPpsi	opened at psi did not open	opened at psi did not open	held at psi		
	Date:	Pass	Pass 🗆	Pass 🗆	Pass 🗆	Pass		
19	Tester Signat	ure: UMW	Failed []	Failed Cer	Failed   tification No.	Failed   524		
Water Di	Owner/Representative Signature:  T Dist White Building Dept Canary Customer - Pink Tester - Goldenrod							