## City of Napoleon

## **BACKFLOW PREVENTION ASSEMBLY TEST RESULTS**

Property Address: 673 Interchange Dr. ZIP: 43545 Business Name: P. G. + E.					
Type (circle one) RP DEVICE INFORMATION DCDA					
Manf/Model: Watts 009 M2QT Size: 2" Serial No. 175956					
Location of Device: <u>in Water mater Hot box</u> Type of Test: Differential Gauge A Sight Tube					
Outlet Reduced Pressure Pressure Vacuum Breaker					
valve	Assembly $\downarrow$			Pressure Vacuum Breaker	
holding  RPM DQ	Double Check Valve		Relief Valve	Air Inlet	Check Valve
failed  RP DC	1st Check	2nd Check	ţţ.		
Test Results	DCpsi	DCpsi	opened at  3 psi	opened atpsi	held atpsi
Pass	RP_ <b>9.6</b> psi		did not	did not	leaked
Data	- 0		open 🗆	open 🗆	
Date: 2-20-02	Pass 🛭	Pass ∠Z Failed □	Pass 🕅 Failed 🗆	Pass □ Failed □	Pass □ Failed □
Repairs & Materials		ja .			
Test After	DC psi	DCpsi	opened at	opened at	held at
Repairs	RPpsi	RPpsi	did not open □	did not open [	leaked
Date:	Pass □ Failed □	Pass []	Pass □ Failed □	Pass   Failed	Pass □ Failed □
Tester Signature: Certification No. 528  Owner/Representative Signature: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					

Water Dist. - White

Building Dept. - Canary

Customer - Pink

Tester - Goldenrod